TAITO AMERICA CORPORATION

1256 ESTES AVENUE • ELK GROVE VILLAGE, IL 60007
(312) 981-1000 • TELEX 253290 CABLE TAMCO ELK GROVE VILLAGE

October 6, 1980

ATTENTION: SERVICE DEPARTMENT MANAGER

Enclosed please find two sets of schematics for Taito "Stratovox."

In the future, our Field Service Department will forward new game schematics to all Service Departments prior to the shipment of new products. This procedure will aid your personnel by providing advance knowledge of our games.


If for any reason your department does not have our previous game schematics, please contact our Field Service Department.


Sincerely,


TAITO AMERICA CORPORATION


Field Service Manager


RAL/dw























PRINTED FACE

NOTE. 3 TRANSISTOR (25C458) NOTE. 4 TRANSISTOR (25C1061)

NOTE. 5 THE RELATION BETWEEN COIN AND CREDIT

i a			SWI						SW2							
· ·		1	2	3	4	5	6	7	1	2	3	4	5	6	7	8
ICOIN	1 PLAY	ON	ON	ON	ON	ON	OFF	OFF	ON	OFF	OFF	OFF	OFF	OFF	ON	OFF
JCOIN	IPLAY	4	3	4	4	3	1,	1	OFF	ON	OFF	4	3	4	1	3
BCOIN	1PLAY	1	2	4	1	2	1	1	5	OFF	ON	4.	1	4	1	3
4COIN	IPLAY	3	3	3	1	3	4	3	3	OFF	OFF	ON	1	1	3	1
					nimphon William			4								
ICOIN	2 PLAY	ON	OFF	OFF	OFF	OFF	ON	ON	OFF	ON						
COIN	3 PLAY	OFF	ON	4	1	1	1	1	4	3	4	4	3	2	4	4
ICOIN	4PLAY	ON	ON	4	2	1	4		1	3	1	3	1	1	4	2

122	100	1 - 10 - 1
23	TCA	1
22	C7	.4
21	C6	4
20	C 5	4
-19	C4	4
18	C3	4
23 22 21 20 19 18 17 16 15 14	CQ	4
16	CI	4
15	IC.7	3
14	10.6	3
13	IC.5	3
12	IC.4	3
12 11 10	IC.3	3
10	IC.2	
9	IC.1	3
9 8 7	02	1
7	C8 C7 C6 C3 C3 C1 IC.7 IC.6 IC.5 IC.4 IC.3 IC.1 D2 D1	n in and and
5 4	TR2 TR2 SW3	V
5	TR.1	AAT/
4	SW.2	AAO 5
3	SW1	7. 5

STRATOVOX + POLARIS.

SAM

11(2

A

SERVICE TIPS

FAST AID HOT LINE: 800-323-0666 EXCEPT ILLINOIS: 312-981-1000 Ext. 215 TELEX: 253290



✓ MANDITORY

81-3

ON FAILURE ONLY

☐ FOR YOUR INFORMATION

ATTN: SERVICE MANAGERS

GAME: STRATOVOX

SUBJECT: -5V FUSE (F4) KEEPS BLOWING

SOLUTION: PROPERLY POLARIZE CAPACITORS

PARTS NEEDED: FOUR 1.5uf CAPACITOR (ELECTROLYTIC)


DISPOSITION OF PARTS: NONE

TAITO AMERICA CORPORATION
1256 Estes Ave., Elk Grove Village, IL 60007

PROCEDURE: INSPECT CAPACITORS AROUND RAM CHIPS AT LOCATION 1C - 3C AND 1D - 3D, SEE IF POLARITY IS CORRECT (REFER TO FIGURE 1) SHADED SIDE IS WERE NOTCH SHOULD BE.

IF CAPACITORS ARE IN WRONG, TAKE THEM OFF AND TEST FOR SHORT, THEN PUT THEM BACK IN ACCORDING TO THE ILLUSTRATION FIGURE 1.

FIGURE 1



TAITO CREDIT PCB POLARIS, STATTOVOX, CRAZY CLIMBER, COLONY 7 ETC. BOARD "D" HAS ONLY I SET OF 4 DIP SWITCHES. FOR 504 PER PLAY, SET SWITCHES As Follows: SW 1 - OFF SWZ - ON SW3 - OFF SW4 - OFF Part # 8000 78 for 31.26 (US.) is available